TEXAS COLLECTION



Tiles & Modern Designs

your style, your home signature vinyls



arena VTX17226509 Pattern Repeat L100 x W99.5 Drop 1/3



marsala VTX16526592 Pattern Repeat L120 x W119.4 Drop 2/3



arteo VTX16926592 Pattern Repeat L100 x W99.5



arteo VTX16926594 Pattern Repeat L100 x W99.5



sorento VTX20526599 Pattern Repeat L100 x W99.5 Reverse Lay



sorento VTX20526582 Pattern Repeat L100 x W99.5 Reverse Lay



pinnacles VTX19526532 Pattern Repeat L100 x W100 Drop 1/2 Reverse Lay



marsala VTX16526532 Pattern Repeat L120 x W119.4 Drop 2/3



odin VTX17026596 Pattern Repeat L100 x W99.5 Reverse Lay



marsala VTX16526598 Pattern Repeat L120 x W119.4 Drop 2/3



palermo VTX5626936 Pattern Repeat L100 x W100 Drop 1/5

before laying on irregular sub-floor



after laving the surface is smooth



Texas backing is designed to be installed on floors with irregularities of up to 2mm deep & 3mm wide. Textile backing takes the shape of the floor, requiring much less prep for easy installation.

:vinyl sheet

thickness

• 2.60mm

texas collection

width wear layer

• 3 & 4m • 0.25mm

slip resistance

• R10

 textile backing installation

warranty

• easy to install • 7 yrs Residential





















tel 03 9401 0888 fax 03 9401 0866

www.signaturefloors.com.au

terms & conditions: Specifications are subject to manufacturing tolerances and may be changed without prior notice. Dye lots may vary in colour from sample and between production lots. All product purchases are subject to Signature Floorcoverings Standard Terms and Conditions of Sale. Please refer to our Installation Guideline, Maintenance Manual and Warranty Document for further clarification.

As per Competition & Consumer Act (CCA): "Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure." 11/2016©